



The clamp must be placed between the copper-foil and the braid.

















Please, do never forget to check, if there is a short-circuit!